

New Features In PRISMS 2000 Ver 7a

- 1) Passwords are no longer required to enter the application.
- 2) Main Menu:
 - a. Import / Export of the local HSC Look Up table.
 - b. Upload DEFI images to the network.
- 3) All import/export routines will zip/unzip files automatically.
- 4) System Configuration screen has paths for:
 - a. Inspector Custom Deck folder
 - b. NWAS Custom Deck folder
 - c. All Archive folders
 - d. SCLISIS Data folder
- 5) Inspection Preparation Screen:
 - a. Indicator to show if loaded SCLISIS UIC matches current Hull UIC.
 - b. Load Master INSCATs by Ship Class (for the Engineering departments):
 - i. CG47
 - ii. DDG51
 - iii. FFG7
 - iv. MCM1
 - v. MHC51
 - vi. PC1
 - vii. SSBN726 (All departments)
 - viii. SSN21 (All departments)
 - ix. SSN688 (All departments)
 - x. SSN774 (All departments)
- 6) DEFI Edit Screen:
 - a. DEFI Edit screen indicates if the current SCLISIS data is loaded.
 - b. Image Capture allows multiple images to be assigned to each DEFI.
 - c. Work Center must be assigned to all DEFI cards.
 - d. W/C button to allow user to select Work Center from a list box (based on SCLISIS).
 - e. Root Cause selector use two list boxes to select from.
 - f. Color coding of EOC scores and updating of stoplight definitions.
 - g. Search 1, 2, 3 work in concert to locate SCLISIS data.
 - h. Point Of Contact (POC) data applied to one card is applied to all cards with the same work center whenever a card is saved.
 - i. Inspector Import allows the user to REJECT selected cards from the import.
 - j. If EOC score is applied from the T/S tab a valid Root Cause must also be applied from the list box selector if the card has no Root Cause assigned.
 - k. Search "1" (HSC Lookup List) screen returns all SCLISIS data or just an HSC.
 - l. Search "3" (Work Center Drilldown) screen auto locates W/C and location if the data is filled in before calling the screen.
 - m. Double clicking on a Pick List grid will show the entire Pick List text (for text line to large to fit on the Pick List screen).
 - n. All cards marked as UNSAT must have Remarks applied.

New Features In PRISMS 2000 Ver 7a

- 7) Browse Screen:
 - a. Double click on Browse grid Work Center field to select from a list box.
 - b. All cards marked as UNSAT must have Remarks applied.
 - c. Toggle between keystroke search of through the noun name field and edit of noun name.
 - d. Double Click on Root Cause field to select from list box.
 - e. Text Search to locate data in any field.
 - f. Right click on Reviewer field to cycle through Review levels (A, I, S)
 - g. Pick List selections retain their special characters and format as a list.
 - h. POC can be applied from the Browse screen
 - i. When applying a Safety to a card in the Browse screen the RAC selector will be called.
- 8) Writer Screen:
 - a. Missing Department button to present a list of all departments that are missing from the current Master Deficiency list.
 - b. Download to INSURV warns the Writer of all missing departments before the user down loads to INSURV.
 - c. Export to CSMP reformats the remarks to remove all formatting to conform to 2-Kilo format rules.
- 9) Custom Deck Usage Status:
 - a. New screen to compare the completed inspection against the supplied NWS Custom Deck to calculate usage of custom deck cards by department.